Provider information on product safety



RIMA Innovations GbR has been run by Richard and Matthias Frische since 2013 The company headquarters is:

Imbuschstr. 14, 90473 Nuremberg, Germany Telephone: +49-170-3633 989, email: mfp@jpf.de

VAT ID no.: DE288116762

Volksbank Lüneburger Heide eG

Account no.: 7302786300 Bank code: 24060300

IBAN DE96240603007302786300

BIC:GENODEF1NBU

RIMA Innovations GbR has mainly been producing and selling heater spare parts since 2012 (1) and repair kits for a cover flap on the Mercedes R230 since 2020 (2).
RIMA Innovations GbR grants a 5-year guarantee on all ist spare parts.

- (1) There is a video guide and a lot of other information for installing the heater spare parts (for old oil heating systems) that is made available to customers on the website www.heizungsteil.de. There is also detailed technical information about the product and the scope of the guarantee granted by RIMA Innovations GbR.
- (2) There is a video guide and a lot of other information for repairing the cover flaps of the Mercedes R230 (this vehicle was produced from 2001 to 2009) that is made available to customers on the website www.kleine-klappe.de. There is also detailed technical information about the product and the scope of the guarantee granted by RIMA Innovations GbR. The repair kit is supplied with installation instructions (in German and English). The website also contains repair instructions in other languages.

Other products developed and produced in-house are offered but are only sold very rarely. Sales share less than 1 per mille in the last 5 years. Information: www.rima-lock.com www.rima-box.com

None of our products pose any danger (based on human judgment).

The instructions and instructions for installation are clear and unambiguous and the need for certain technical skills for installation and assembly is pointed out.

I am responsible for these products and their product safety.

Matthias Frische

Nuremberg, September 9, 2024

This is an automated translation (Google Translate German->English) of the German original of this document. Corrections have been applied where the automatic translation was clearly wrong.